

RAUMPLUS

CARE AND MAINTENANCE OF SLIDING DOORS AND PANELS

Glass

Take special care during the initial cleaning, the construction period or when glass surfaces are severely soiled. This prevents glass damage caused by abrasive contaminants. First, flush glass surfaces with clean water to remove as many contaminants as possible. With the glass surfaces still heavily wetted, carefully work a squeegee from top to bottom removing excess water. Ensure that any remaining abrasive materials do not become trapped between the glass surface and the rubber squeegee; otherwise, the glass surfaces may become scratched.

Then, clean the glass with a clean, soft, grit-free cloth and a mild, non-abrasive, non-alkaline

cleaning solution. Rinse immediately with clean water and remove any excess water from the glass surfaces with a squeegee. For routine cleaning, use a mild soap or detergent and lukewarm water. Uniformly spray the cleaning solution or apply it with a clean, soft, grit-free applicator and rinse thoroughly. Dry the glass surface with a clean, grit-free cloth or a squeegee. Do not allow any metal or hard parts of the cleaning equipment to contact the glass surfaces.

Aluminum Frame

Wipe down with damp cloth as needed.

Brush Gasket

Vacuum with upholstery brush/attachment quarterly or as needed.

Over time a dark smudge may appear where the brush gasket have contact with the wall. This is not color rubbing of the brush gasket, but dust being pressed against the wall. Remove by cleaning wall surface as recommended by installer of wall surface.

Bottom tracks

Vacuum as needed.

Adjustments

Adjust per installation Instructions as needed.